
Ethernet Direct Between a 5020 Product and a 7020 node

If running firmware version 7.17 or newer on both a 5020-M and a 7020 node, then a 5020-M will communicate with a 7020 node via Ethernet Direct. However, if the 5020 is an “E” or an “LNK” model, then regardless of firmware, communication via Ethernet Direct will not work.

If running firmware version 7.16 or any variation of 7.16, then communication between any 5020 unit and a 7020 node via Ethernet Direct will NOT be possible.

FAQETHDIR5020-700005202015

Rev. 01